

	Type	L #	Hits	Search Text	DBs
1	BRS	L3	55263	(pump or actuator) same disc	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
2	BRS	L2	100	417/233	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT
3	BRS	L1	671	137/223	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT

	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
1	2005/06/06 12:02			
2	2005/06/06 12:02			
3	2005/06/06 12:04			

	Type	L #	Hits	Search Text
1	BRS	L1	8	"1169705".pn.
2	BRS	L2	6	"1349671".pn.
3	BRS	L3	2	"5342177".pn.
4	BRS	L4	2	"5626072".pn.
5	BRS	L5	2	"5257553".pn.
6	BRS	L6	2	"5397144".pn.
7	BRS	L7	2	"5318317".pn.
8	BRS	L8	564	152/415
9	BRS	L12	325	152/427
10	BRS	L11	61	152/419

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:36			
2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:39			
3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:41			
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:44			
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:45			
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:46			
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:49			
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:49			
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 07:50			
10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:05			

	Type	L #	Hits	Search Text
11	BRS	L13	4756	(tire or wheel) same (inflation or inflating) same (device or apparatus)
12	BRS	L14	3724	(tire or wheel) same (inflation or inflating) same (system or apparatus)
13	BRS	L15	464	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping)
14	BRS	L16	92	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate
15	BRS	L18	2	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve same bicycle
16	BRS	L22	0	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve and "70"/\$.ccls.
17	BRS	L23	0	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve and "24"/\$.ccls.

	DBs	Time Stamp	Comments	Error Definition	Errors
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:06			
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:34			
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:35			
14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:31			
15	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:07			
16	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:09			
17	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:09			

	Type	L #	Hits	Search Text
18	BRS	L20	3	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve and "280"/\$.ccls.
19	BRS	L21	14	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve and "417"/\$.ccls.
20	BRS	L19	22	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve and "152"/\$.ccls.
21	BRS	L17	78	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same valve
22	BRS	L24	0	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same plate same (selectively or selective) same (engage or engagement)

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
18	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:09			
19	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:10			
20	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:12			
21	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:15			
22	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:32			

	Type	L #	Hits	Search Text
23	BRS	L25	0	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same disc same (selectively or selective) same (engage or engagement)
24	BRS	L26	25	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) same disc
25	BRS	L27	81	280/201
26	BRS	L9	280	152/416
27	BRS	L28	1049	280/288.4
28	BRS	L29	1	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) and 280/288.4
29	BRS	L30	0	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) and 280/304.2

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
23	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:32			
24	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:33			
25	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 08:33			
26	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:01			
27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:03			
28	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:02			
29	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:02			

	Type	L #	Hits	Search Text
30	BRS	L31	3	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or pumping) and 280/201
31	BRS	L32	45	280/288.4 and pump
32	BRS	L10	166	152/418
33	BRS	L33	2	"5626072".pn.
34	BRS	L34	55	("0540252" "0559418" "0596223" "0624417" "0652997" "0681565" "0744483" "0797447" "0868658" "0932371" "1169705" "1349225" "1417355" "1455646" "1760346" "2472647" "2597829" "2662261" "3053194" "3233554" "3283997" "3451276" "3510923" "3517652" "3699961" "4137020" "4301826" "4462768" "4583925" "4677328" "5113747") .PN.
35	BRS	L35	4	("540252") .URPN.

	DBs	Time Stamp	Comments	Error Definition	Errors
30	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:03			
31	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:03			
32	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:45			
33	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 09:46			
34	US-PGPUB; USPAT; USOCR	2005/06/06 09:46			
35	USPAT	2005/06/06 10:09			

	Type	L #	Hits	Search Text
36	BRS	L36	1	"5342177".pn.
37	BRS	L37	5	("5342177").URPN.
38	BRS	L38	23	("1127079" "1679505" "1744405" "1776933" "1875874" "2141542" "2161384" "2211935" "2256469" "2317636" "2415618" "5342177").PN.
39	BRS	L39	1	"5257553".pn.
40	BRS	L40	3	("5257553").URPN.
41	BRS	L41	25	("2768836" "3354975" "3948424" "3989261" "4032168" "4046396" "4057264" "4129317" "4274647" "4327928" "4506753" "4512592" "4524844" "4561669" "4687072" "4735276" "5086866" "5257553" "5715903" "5829773" "5855388" "5947498" "6017047").PN.
42	BRS	L42	2	"1349671".pn.
43	BRS	L43	0	("1349671").URPN.

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
36	USPAT	2005/06/06 10:09			
37	USPAT	2005/06/06 10:09			
38	US-PGPUB; USPAT; USOCR	2005/06/06 10:14			
39	US-PGPUB; USPAT; USOCR	2005/06/06 10:14			
40	USPAT	2005/06/06 10:14			
41	US-PGPUB; USPAT; USOCR	2005/06/06 10:16			
42	US-PGPUB; USPAT; USOCR	2005/06/06 10:16			
43	USPAT	2005/06/06 10:16			

	Type	L #	Hits	Search Text
44	BRS	L44	0	("1349671").URPN.
45	BRS	L45	0	("1349671").URPN.
46	BRS	L46	0	("1349671").URPN.
47	BRS	L47	6	"1792123"
48	BRS	L48	0	("1792123").URPN.
49	BRS	L49	1	"5397144".pn.
50	BRS	L50	46	("0540252" "0559418" "0596223" "0624417" "0652997" "0681565" "0744483" "0797447" "0868658" "1169705" "1349225" "1455646" "1760346" "2472647" "2662261" "3053194" "3233554" "3283997" "3451276" "3510923" "3517652" "4137020" "4462768" "4677328" "5318317").PN.
51	BRS	L51	5	("5318317").URPN.
52	BRS	L52	1	"5318317".pn.

	DBs	Time Stamp	Comments	Error Definition	Errors
44	USPAT	2005/06/06 10:17			
45	USPAT	2005/06/06 10:18			
46	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:19			
47	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:19			
48	USPAT	2005/06/06 10:19			
49	USPAT	2005/06/06 10:19			
50	US-PGPUB; USPAT; USOCR	2005/06/06 10:20			
51	USPAT	2005/06/06 10:25			
52	USPAT	2005/06/06 10:26			

	Type	L #	Hits	Search Text
53	BRS	L53	5	("5318317").URPN.
54	BRS	L54	46	("0540252" "0559418" "0596223" "0624417" "0652997" "0681565" "0744483" "0797447" "0868658" "1169705" "1349225" "1455646" "1760346" "2472647" "2662261" "3053194" "3233554" "3283997" "3451276" "3510923" "3517652" "4137020" "4462768" "4677328" "5318317").PN.
55	BRS	L55	325	152/427
56	BRS	L57	100	417/233
57	BRS	L58	100	417/233
58	BRS	L59	514	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or actuator)
59	BRS	L60	24	(tire or wheel) same (inflation or inflating) same (device or apparatus) same (pump or actuator) same clutch

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
53	USPAT	2005/06/06 10:26			
54	US-PGPUB; USPAT; USOCR	2005/06/06 10:28			
55	US-PGPUB; USPAT; USOCR	2005/06/06 10:31			
56	US-PGPUB; USPAT; USOCR	2005/06/06 10:32			
57	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:32			
58	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:35			
59	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:37			

	Type	L #	Hits	Search Text
60	BRS	L61	257	417/550
61	BRS	L62	0	301/15.1
62	BRS	L64	97	301/124.2
63	BRS	L63	470	301/105.1
64	BRS	L65	248	137/224

	DBs	Time Stamp	Co mm en ts	Er ro r De fi ni ti on	Err ors
60	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:38			
61	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:39			
62	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:39			
63	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:57			
64	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	2005/06/06 10:57			